
NPS-61-85-004

AD-A157 278

NAVAL POSTGRADUATE SCHOOL Monterey, California



Reproduced From Best Available Copy

20000811084

A FLASH WHEN FACILITY FOR THE NAVAT FOR TO ADUATE SCHOOL

X. K. Maruyana and E. C. Zurey, Jr.

June 1985

Technical Report

Approved for public release, distribution unlimited

Prepared for: Naval Postgraduate School Monterey, CA 93943



G

NAVAL POSTGRADUATE SCHOOL MONTEREY, CALIFORNIA

Rear Admiral Robert H. Shumaker Superintendent

David A. Schrady Provost

Reproduction of all or part of this report is authorized.

This report was prepared by:

XAVIER K. MARRYAMA
Adjunct Professor of Physics

Edward C. Zurry fr. EDWARD C. ZUREY, OJR. Lieutenant, USN

Reviewed by:

Released by:

GORDON E. SCHACHER, Chairman Department of Physics JOHN N. DYER
Dean of Science and Engineering

Accession For

NTIS GPA&I
DTIC TAB
Unannounced
Justification

By____
Distribution/

/voisability Codes

// in and/or

Justification

UNCLASSIFIED

なのは最からなるのではなるのでは、Mana かっていた。 Mana からのでも見り

事からなって、関係を与うなというというないからいというないのからないのである。

SECURITY CLASSIFICATION OF THIS PAGE (When Date Enter

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
NPS-61-85-004	2 8 EATALOS NUMBER
4. TITLE (and Subtitio)	S. TYPE OF REPORT & PERIOD COVERED
A Flash X-Ray Facility for the	Technical Report
Naval Postgraduate School	6. PERFORMING ORG. REPORT HUMBER
7. AUTHOR(e)	S. CONTRACT OF GRANT HUMBERY
X. K. Maruyama and E. C. Zurey, Jr.	·
3. PERFORMING ORGANIZATION NAME AND ADDRESS	18. PAGERAN ELEMENT, PAGIECT, YARR
Naval Postgiaduate School	
Monterey, CA 93943	
11. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE
	June 1985
Naval Postgraduate School	15. HUMBER OF PAGES
Monterey, CA 93943	15 18. SECURITY CLASS, (of this report)
14. BONITORING AGENCY NAME & AGCRESSIT BIRDER AND COMMING OFFICE	in second v contact (or and report
	UNCLASSIFIED
	THE DECLAMPICATION/DOMERADING
16. DISTRIBUTION STATEMENT (of this Report)	
Approved for public release; distribution unlim	Ited
17. DISTRIBUTION STATEMENT (of the abovest entered in Block 28, if different fro	n Appell
•	
18. SUPPLEMENTARY HOTES	
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)	
Flash X-Ray Accelerator, Radiation Shielding; Occ Radiological Safety	cupational Safety,
A Flash X-ray accelerator acquired by the Naval I discussed. Safety considerations in siting this	

A FLASH X-RAY FACILITY FOR THE NAVAL POSTGRADUATE SCHOOL

X. K. Maruyama and E. C. Zurey, Jr.

Department of Physics Naval Postgraduate School Monterey, CA 93943

INTRODUCTION

A Pulsar Model 112A flash X-ray machine has been acquired by the Naval Postgraduate School. This brief report describes the technical aspects of the accelerator and provides documentation so that interested and affected parties may be informed on safety precautions, potential uses and practical considerations for the effective utilization of a major reasource for education and research.

This report is <u>not</u> required by NAVPGSCOLINST 5100.5A and 5100.6A which pertains to the radiation protection program ^{1,2} at NPS, but is submitted as a matter of courtesy and prudence as some aspects of the use of the flash X-ray machine may fall within the responsibility of safety organizations at NPS. This document constitutes a report to the Safety Manager, the Radiation Protection Officer and the Radiological Safety and Isotopes Committee (RSIC). The device does not fall under the licensing authority of the Nuclear Regulatory Commission as radioactive sources are not involved.

ライ 動物のでは、自然のためを加えるもので

The Naval Postgraduate School has had a long history of education, training and research involving ionizing radiation, NPS has had active programs with a Van de Graaff generator, a reactor, radioactive sources, X-ray machines and a linear electron accelerator. These programs have related to subjects in material science, nuclear reaction and structure studies, solid state physics, beam transport, interaction of radiation with matter and with coherent radiation. Currently the most active program is at the linear electron accelerator which over twenty years has produced some 75 theses. The flash X-ray machine was obtained to expan: and complement the capabilities of the linear electron accelerator in the fields of radiation effects on electronic devices, charged particle transport in tenuous and bulk materials, coherent radiation and the study of the properties of intense charge particle beams.

The complementary nature of the flash X-ray machine and the linear electron accelerator are evident when one compares the characteristics of the two accelerators (Table 1). The linac is capable of producing high energy, low current electron beams, whereas the flash X-ray is capable of producing low energy, high current electron beams. Both accelerators are to be used in the radiation effects and space effects programs.

Table 1
Characteristics of Accelerators at the
Naval Postgraduate School

· · · · · · · · · · · · · · · · · · ·	LINAC	PULSAR 112A
Max. Energy	100 MeV	1.75 MeV
Pulse Ref. Rate	60 Hz	1/hr (max 4/hr)
Power Source	RF Klystrons	Marx Bank
Peak Current	-1 OmA	35 kiloamperes
Average Current	-1 mA	not meaningful
Pulse Width	1 msec	30 nsec.

A detailed study³ has been conducted describing the flash X-ray machine and its impact on the Naval Postgraduate School. The reader is referred to the study for details not covered in this brief report.

PULSAR 112A ELECTRON BEAM/FLASH X-RAY SYSTEM

The Pulsar 112A Electron Beam/Flash X-Ray System is a high power, low maintenance, high reliability, relatively low cost, radiation and electron beam source manufactured by Pulsar Products, Inc., a subsidiary of Physics International Co. Basically it consists of a Marx bank of capacitors charged in parallel and then discharged in series to provide the high accelerating voltage for the electron beam. There is a pulse forming network called the Blumlein which provides a fast pulse

of electrons into an impedance matched load. The active components of the Pulsar 112A are encased in an oil filled tank. Figure 1 illustrates the active components of the Pulsar 112A. Pertinent machine characteristics are given in Table 2.

Table 2
Pulsar 112A Characteristics

Peak Voltage	•	1.75 MV
Peak Current		35 kiloampere
Pulse Energy Content		1.6 kilojoule
Pulse Width		30 x 10 ⁻⁹ sac
Pulse risetime		15 x 10 ⁻⁹ sec
Dimensions:		·
length		19.7 ft
neight		6 ft
width	T.	4.3 ft
weight (with oil)		11,700 1b

SITE SELECTION

Ref. 3 considered installation of the Pulsar 112A in several sites in Halligan Hall. These are designated as sites 1 through 4 in Figure 2. After discussion with the Aeronautical Engineering Department, site 5 has been suggested as an installation site. The choice of adequate site location are dictated by radiation and industrial safety, floor loading, crane access, experimental program space, manpower and other resources requirements.

The Pulsar 112A needs to be located in Halligan Hall for the following reasons: a) Many of the experiments require the same equipment so that resources can be shared with the linac. example, vacuum system components, dosime: y equipment, storage and fast real time oscilloscopes and Nuclear Instrumentation Module (NIM) equipment can be shared. Duplication of these resources could cost several hundred thousand dollars. b) Personnel associated with the linac have experience with ionizing radiation and accelerators. At a minimum, a dedicated professional scientist and one or two technicians would have to be hired in addition to the existing staff if a physically separate location were to be chosen. c) Radiation safety would be enhanced by a central location for sources of ionizing radiation. Physical proliferation of ionizing radiation sources would strain the resources of the RSIC, Radiation Safety Officer and the Safety Manager. d) Educational opportunities would be enhanced by utilizing the complementary characteristics of the linac and the Pulsar 112A. Presently, thesis students reside in room 023 of Halligan Hall and form a positive feedback network among themselves by learning from related experiences. educational opportunity is induced by the environment and is not

The linear electron accelerator is located in Halligan Hall.

Among the sites considered in Halligan Hall, site 2 was deemed inadequate because of marginal floor loading capacity and the nonavailability of an overhead crane. Physical location of

available in a classroom instruction situation.

the Pulsar 112A into site 2 would require considerable reconstruction of some of the structure in room 031. Site 1 was deemed inadequate because of lack of space for propagation and laser excitation experiments. These topics are of current interest in military research. Site 1 is the former 300 ton sest loading machine pit and is the most physically restrictive.

Site 3 is the ideal location for the Pulsar 112A. Site 4 and 5 are adequate.

SAFETY CONSIDERATION

Radiation

One important difference between the flash X-ray machine and the linear electron accelerator is that because of the low energy of the electrons no induced radioactivity is possible with the Pulsar 112A.

In considering radiation safety, our goal was to insure that no area accessible to the general public would be exposed to radiation in excess of the permissible dose to the general public according to the Code of Federal Regulation, Title 10, Part 20. This limit is 0.5 rems/year. Ref. 3 details the assumptions and calculations to achieve these considerations, but the final shielding configurations will be determined by actual measurements of the exposure in public access areas. In summary, with a one inch lead housing about an irradiation area and a block house made of 15" of concrete around the accelerator experimental area, no public access area receives more than one

percent of the allowable radiation limits permitted by the Code of Federal Regulations. Most areas would be exposed to radiation several orders of magnitude smaller. Even removing the housing about an irradiation sample the radiation exposure in public access areas are within the allowable limits. The reader is referred to Ref. 3 for details for the calculation of results in Table 3.

Table 3
Calculated Radiation Levels (mrem/pulse) Throughout Halligan Hall for Site 5.

w/o lo	cal shielding	w/local shielding
Restricted Area Perimeter	0.24-0.02	2.4x10 ⁻² -2x10 ⁻⁴
Ground Floor Balcony-Overhead	0.24	2.4x10 ⁻³
Ground Floor Balcony-Across	0.003	3x10 ^{-s}
Basement		
Ground Floor Balcony-Lounge	0.001	1x10 -5
Area	•	
CFR Limit with Maximum Usage	e 0.24	· · · · · · · · · · · · · · · · · · ·

Interlock and Warnings.

Access to the experimental area would be interlocked with the Pulsar 112A control panel, so that it is not possible to charge or discharge the Marx bank generators while the area is open.

Whenever the machine is capable of producing an electron beam, a flashing warning beacon would be visible in the laboratory area.

"Panic" buttons would be accessible in the experimental area to

prevent firing of the Pulsar 112A if personnel are in experimental areas when the machine is capable of operation.

Noxious Gas

Ozone is produced whenever the air is icnized. It is possible to create a hazardous concentration in a small volume if the air is confined. Although the experimental area is of large enough volume to prevent hazardous concentration of ozone, as a further precautionary measure a ventilation system will be installed.

Electrical

High voltage is always a potential hazard in an experimental environment. Access to HV areas will be confined to qualified personnel only. Any work with potential HV components will be done by two people.

Fire Protection

Materials bombarded by intense electron beams will obsorb electron energy as heat. The accelerator components are immersed in an electrically insulating oil. Good housekeeping and the availability of fire extinguishers and life support equipment will eliminate fire hazard potential.

SAFETY MONITORING

Personnel associated with the facility will be participants in the LiF TLD program.² Experimental and public areas will be monitored with TLD dosimeters to insure that radiation exposure are in compliance with safety limits.⁴

To insure independent assessment of safety aspects, the following activities monitor the accelerator laboratory:

- 1. NPS Safety Office will involve itself with:
- a) design review with emphasis on occupational safety.

 This document is part of the effort to provide information to the safety office.
- b) industrial hygiene review in consultation with NRMC, Oakland.
- c) consultations with the Naval Environmental Health Center, Norfolk, VA.
- 2. The manufacturer, Physics International, employs a shielding consultant available to us at no cost to review our facility plans.
- 3. The Naval Postgraduate School participates in the LiF TLD program administered by NRMC, Bethesda.
- 4. The Naval Postgraduate School is inspected periodically by the Naval Energy and Environmental Support Activity, Yorktown, VA.
- 5. The Radiological Safety Officer inspects and monitors the activities of the facility.

6. The Radiological Safety and Isotopes Committee oversees all aspects of radiological safety at the Naval Postgraduate School.

SUMMARY

This report has described briefly the technical and safety aspects of the Pulsar 112A acquired by the Naval Postgraduate School. With a little planning it will be a safe, effective machine enhancing existing capabilities and creating new opportunities for research and education.

*Permanent Address - National Bureau of Standards, Gaithersburg, May 20899

REFERENCES

- 1. NAVPGSCOL INSTRUCTION 51005A, "Use of Radioisotopes at the Naval Postgraduate School," 10 Sept 1979.
- 2. NAVPGSCOL INSTRUCTION 51006A, "Administration of Lithium Flouride Thermoluminescent Dosimetry Program," 10 Sept 1979.
- 3. E. C. Zurey, "Facilities Requirements for a Flash X-Ray Machine," M. S. Thesis, Naval Postgraduate School, 1985 (unpublished).
- 4. U.S. Nuclear Regulatory Commission, <u>Code of Federal</u>

 <u>Regulations: Title 10, Chapter 1, Part 20, U.S. Government</u>

 Printing Office, Washington, D.C., 1984.




Figure 1: A Block Diagram of a Pulse Charged System




Figure 2: Basement Plan of Halligan Hall

DISTRIBUTION LIST

Chairman Physics Department, Code 61 Naval Postgraduate School Monterey, CA 93943		2
Chairman Aeronautics Department, Code 67 Naval Postgraduate School Monterey, CA 93943		. 2
Chairman Mechanical Engineering Departme Naval Postgraduate School Monterey, CA 93943	nt, Code 69	
Dr. X. K. Maruyama Rm. B108, Bldg 245 National Bureau of Standards Gaithersburg, MD 20899		3
LT. E. C. Zurey, Jr. 4653 Boxford Road Virginia Beach, VA 23456		1
Safety and Occupational Health Code 005 Naval Postgraduate School	Manager	2
Monterey, CA 93943		•
Prof. J.R. Neighbours Prof. F. R. Buskirk Prof. K. E. Woehler		1 1 1
Mr. D. Snyder Prof. K. C. Dimiduk Physics Department, Code 61		2
Naval Graduate School Monterey, CA 93943		
Mr. R. A. Smith H23	-	1
Naval Surface Weapons Center 10901 New Hampshire Avenue		. •
Silver Spring, MD 20903		
Radiological Safety and Isotope Code 61	S COMMITTEE	
Naval Postgraduate School		

Defense Technical Information Center Cameron Station	2
Alexandria, VA 22314	
Dudley Knox Library	2
Code 0142	
Naval Postgraduate School Monterey, CA 93943	
Office of Research Administration	1
Code 012A	
Naval Postgraduate School	
Monterey, CA 93943	

とのないできないと言葉のマントのは言うとうないでき

END

FILMED

9-85

DTIC